



Vending Care....

Work Order Details

Job Details

Asset No 01645 **Job Creation Date** 12/15/2016 11:40:10 AM

Job Start Location **Job End Location** No Location Found

Job Start Date **Job Finish Date** 12/15/2016 2:48:00 PM

Customer Contact No 9136160814 **Customer Email**

Present Status Completed

Remarks ok

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	50.00	0.00	82.00	10439.00
Latte with Fresh milk	9.00	0.00	80.00	8818.00
Cappucinno with Fresh milk	50.00	0.00	82.00	1153.00
Americano	12.00	0.00	79.00	319.00

Job Images




(http://vendingcare.in/vendingcare/Images/JobImages/72005_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/72005_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/72005_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/72005_4.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓

Parameter Type	Parameter	value
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015