Vending Care....



Work Order Details

Job Details

Asset No 26648 Job Creation Date 4/21/2017 10:10:48 AM

Job Start Location No Location Found Job End Location No Location Found

Job Start Date 4/21/2017 10:35:20 AM Job Finish Date 4/21/2017 12:15:46 PM

Customer Contact No 7838965715 Customer Email manish.rawat803@gmail.com

Present Status Completed

Remarks

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	46.00	45.00	79.00	13312.00
Latte with Fresh milk	23.00	6.80	78.00	546.00
Cappucinno with Fresh milk	34.00	7.10	77.00	1310.00
Americano	73.00	7.10	76.00	387.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/95740_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/95740_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/95740_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/95740_4.png



(http://vendingcare.in/vendingcare/Images/JobImages/95740_5.png)

Work Order Checklist

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		

Parameter Type	Patameter	value
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	1
HYGIENE		
	Cleaning and operational instruction sticker	8
PART CLEANED		
	Mixing Unit	S
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	S
	Silicon Tubes	S
	Dispensing valves	S
	Canisters	S
	M/C Body (inner and outer)	S
	Stream Exhaust hose pipe	S
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	✓
	Application of cockroach Gel	S

Signature



BACK TO LIST (/VENDINGCARE/WORKORDER/INDEX?LENGTH=3)

copyright 2015