



Vending Care....

Work Order Details

Job Details

Asset No 02134 **Job Creation Date** 3/2/2017 6:21:42 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 3/2/2017 6:24:23 PM **Job Finish Date** 3/2/2017 6:29:12 PM

Customer Contact No 9990882884 **Customer Email** subros .c51 noida phase.2

Present Status Completed

Remarks new installation

Ingredient Details

| Ingredient | Water | Premix | Temperature | Counter |
|-----------------|-------|--------|-------------|----------|
| Hot Lemon Tea | 94.00 | 11.75 | 83.20 | 36616.00 |
| Tea Bag with DW | 94.00 | 11.78 | 84.60 | 89040.00 |
| Coffee | 93.00 | 12.85 | 85.00 | 67904.00 |
| Soup | 95.00 | 6.45 | 82.00 | 21316.00 |

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/86786_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86786_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86786_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86786_4.png)

Work Order Checklist

| Parameter Type | Parameter | value |
|-----------------|--|-------|
| SAFETY | | |
| | Good Condition of 3 pin 15 Amp Plug socket | ✓ |
| | Effective Earthing | ✓ |
| BRANDING | | |
| | No of gell spots found | ✗ |

| Parameter Type | Parameter | value |
|---------------------|--|-------|
| | Overall body condition | ✓ |
| | Brand and keypad stickers in good condition | ✗ |
| HYGIENE | | |
| | Cleaning and operational instruction sticker | ✓ |
| PART CLEANED | | |
| | Application of cockroach Gel | ✗ |
| | Availability of Canister Elbow | ✗ |
| | Working of Exhaust Fan | ✓ |
| | Stream Exhaust hose pipe | ✓ |
| | M/C Body (inner and outer) | ✓ |
| | Canisters | ✓ |
| | Dispensing valves | ✓ |
| | Silicon Tubes | ✓ |
| | Boiler Tank and Water Tank | ✓ |
| | Dispensing Nozzle | ✓ |
| | Drip Try | ✗ |
| | Mixing Unit | ✓ |

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015