



## Vending Care....

## Work Order Details

## Job Details

**Asset No** 28404 **Job Creation Date** 2/22/2017 10:51:00 AM

**Job Start Location** **Job End Location** No Location Found

**Job Start Date** **Job Finish Date** 2/22/2017 12:34:16 PM

**Customer Contact No** 9811392219 **Customer Email**

**Present Status** Completed

**Remarks** installation ok

## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea Bag with DW	95.00	6.30	64.00	6.00
Latte with DW	25.00	5.31	69.00	4.00
Cappucinno with DW	30.00	6.48	73.00	1.00

## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/85022\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/85022_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/85022\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/85022_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/85022\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/85022_3.png))

## Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✗
	No of gell spots found	✗
HYGIENE		
	Cleaning and operational instruction sticker	✓

Parameter Type	Parameter	value
PART CLEANED		
	Mixing Unit	✘
	Drip Try	✘
	Dispensing Nozzle	✘
	Boiler Tank and Water Tank	✘
	Silicon Tubes	✘
	Dispensing valves	✘
	Canisters	✘
	M/C Body (inner and outer)	✘
	Stream Exhaust hose pipe	✘
	Working of Exhaust Fan	✘
	Availability of Canister Elblow	✘
	Application of cockroach Gel	✘

**Signature**



[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015