



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 32570 **Job Creation Date** 3/8/2017 5:04:57 PM  
**Job Start Location** No Location Found **Job End Location** No Location Found  
**Job Start Date** 3/8/2017 5:19:19 PM **Job Finish Date** 3/8/2017 5:38:38 PM  
**Customer Contact No** 9810582003 **Customer Email** titanggng@gmail.com  
**Present Status** Completed

**Remarks** TSD920% wait for power.table&water 1:30 hours


### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Soup	0.00	0.00	70.80	934.00
Coffee	84.00	11.30	70.40	625.00
Cardamom Tea	86.00	11.20	70.80	1192.00

### Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/87830\_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87830\_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87830\_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87830\_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87830\_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87830\_6.png)

### Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓

Parameter Type	Parameter	value
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Tray	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	✓
	Application of cockroach Gel	✗

**Signature**


[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015