



## Vending Care....

## Work Order Details

## Job Details

**Asset No** 01301 **Job Creation Date** 11/28/2016 4:23:24 PM

**Job Start Location** No Location Found **Job End Location** No Location Found

**Job Start Date** 11/28/2016 4:23:55 PM **Job Finish Date** 11/28/2016 4:44:32 PM

**Customer Contact No** 9654135560 **Customer Email** tiplpmc@gmail.com

**Present Status** Completed

**Remarks** installation done ok

## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Hot Lemon Tea	94.00	11.78	83.20	12009.00
Tea Bag with DW	94.00	11.85	84.60	27917.00
Coffee	93.00	12.85	85.00	11945.00

## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/68420\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/68420_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/68420\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/68420_2.png))




([http://vendingcare.in/vendingcare/Images/JobImages/68420\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/68420_3.png))

## Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓

Parameter Type	Parameter	value
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

**Signature**



[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015