



Vending Care....

Work Order Details

Job Details

Asset No 26497 **Job Creation Date** 2/15/2017 5:00:50 PM

Job Start Location Internal Road, Gurugram, India **Job End Location**

Job Start Date 2/15/2017 5:25:06 PM **Job Finish Date** 2/15/2017 5:58:21 PM

Customer Contact No 7838675709 **Customer Email** no email id

Present Status Completed

Remarks tds 50


Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Soup	90.00	6.30	74.80	24.00
Coffee	90.00	11.20	76.30	26.00
Tea Bag with DW	90.00	10.10	73.10	16.00
Cardamom Tea	90.00	11.15	75.70	25.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/83860_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/83860_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/83860_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/83860_4.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓

Parameter Type	Parameter	value
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015