



Vending Care....

Work Order Details

Job Details

Asset No 26441 **Job Creation Date** 4/21/2017 12:05:07 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 4/21/2017 12:05:28 PM **Job Finish Date** 4/21/2017 12:13:14 PM

Customer Contact No 7827913608 **Customer Email**

Present Status Completed

Remarks

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Coffee	80.00	11.20	73.50	23053.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/95792_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/95792_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/95792_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/95792_4.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✗
	No of gell spots found	✗
HYGIENE		

Parameter Type	Parameter	value
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

Signature

SUR
A J

[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015