



Vending Care....

Work Order Details

Job Details

Asset No 28351 **Job Creation Date** 3/25/2017 11:14:29 AM
Job Start Location 19, New Delhi, India **Job End Location** 19, New Delhi, India
Job Start Date 3/25/2017 11:15:51 AM **Job Finish Date** 3/25/2017 12:42:40 PM
Customer Contact No 9899145041 **Customer Email** piyushsingh.3321@gmail.com
Present Status Completed

Remarks


Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Strong Tea	62.00	34.00	76.70	5.00
Latte with Fresh milk	70.00	13.00	77.50	7.00
Cappucinno with Fresh milk	65.00	17.00	77.80	10.00
Americano	52.00	18.00	80.50	2.00
Light Tea	68.00	28.00	76.40	8.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/90354_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90354_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90354_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90354_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90354_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90354_6.png)

Work Order Checklist

Parameter Type	Parameter	value
----------------	-----------	-------

SAFETY

Effective Earthing	✓
Good Condition of 3 pin 15 Amp Plug socket	✓

BRANDING


Brand and keypad stickers in good condition	✓
Overall body condition	✓
No of gell spots found	✓

HYGIENE

Cleaning and operational instruction sticker	✓
--	---

PART CLEANED

Mixing Unit	✓
Drip Try	✓
Dispensing Nozzle	✓
Boiler Tank and Water Tank	✓
Silicon Tubes	✓
Dispensing valves	✓
Canisters	✓
M/C Body (inner and outer)	✓
Stream Exhaust hose pipe	✓
Working of Exhaust Fan	✓
Availability of Canister Elbow	✓
Application of cockroach Gel	✓

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015