



Vending Care....

Work Order Details

Job Details

Asset No 27252 **Job Creation Date** 4/26/2017 2:10:36 PM

Job Start Location 601, ?? ??????, India **Job End Location**

Job Start Date 4/26/2017 2:14:00 PM **Job Finish Date** 4/26/2017 3:17:02 PM

Customer Contact No 8287146216 **Customer Email**

Present Status Completed

Remarks 30 milk bag delivered in Wingify

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	45.00	45.00	85.00	9.00
Latte with Fresh milk	25.00	1.10	85.00	4.00
Cappucinno with Fresh milk	25.00	1.40	85.00	4.00
Americano	70.00	1.80	85.00	6.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/96893_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/96893_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/96893_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/96893_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/96893_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/96893_6.png)

Work Order Checklist

Parameter Type	Patameter	value
SAFETY		

Parameter Type	Parameter	value
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✗
PART CLEANED		
	Mixing Unit	✓
	Drip Tray	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

Signature


[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015